CASE STUDY

Site description	Garbage containers collection truck
Treatment location	Interior of the truck where the garbage containers are collected
Location description	Standard collection truck
Characteristic smells	Garbage, organic breaking down
Active agent used	3 Gelactiv [®] cartridges (2 Gelactiv [®] AFG + 1 Gelactiv [®] B3)
Diffusion technology applied	Smellmeister® Truck linked to a diffusion ramp installed inside and in the back of the truck
Treatment renewal rate	1 cartridge per month (33%)

 $\underline{\textit{Note}}\textsc{:}$ The Smellmeister $^{\!8}$ Truck device is supplied by the truck (24V) and only works when the truck is running.

View of the Smellmeister® Truck installed underneath the truck:





In depth view of the Smellmeister® Truck device underneath the truck:



View of the diffusion ramp installed inside and in the back of the truck:



